
Section 22 Connecticut

Appendix O

Connecticut Coastal Structures Inventory Study - Phase III

January 1990



**US Army Corps
of Engineers**
New England Division

REPORT DOCUMENTATION PAGE			Form Approved OMB No. 0704-0188	
<small>Public reporting burden for this collection of information is estimated to average 1 hour of response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.</small>				
1. AGENCY USE ONLY (Leave blank)	2. REPORT DATE January 1990	3. REPORT TYPE AND DATES COVERED Section 22		
4. TITLE AND SUBTITLE Section 22, Connecticut Coastal Structures Inventory Study, Phase III, Appendix O, Westport Quadrangle, Records of Structures With Photographs			5. FUNDING NUMBERS	
6. AUTHOR(S) U.S. Army Corps of Engineers New England Division				
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) U.S. Army Corps of Engineers, New England Division 424 Trapelo Road Waltham, MA 02254-9149			8. PERFORMING ORGANIZATION REPORT NUMBER	
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) Connecticut Department of Environmental Protection Coastal Resources Management Division			10. SPONSORING/MONITORING AGENCY REPORT NUMBER	
11. SUPPLEMENTARY NOTES				
12a. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release Distribution is unlimited			12b. DISTRIBUTION CODE	
13. ABSTRACT (Maximum 400 words) This Appendix O report contains data gathered during Phase III of the ongoing project to inventory erosion and flood control structures on the northern shore of Long Island Sound within the statutory boundaries of the State of Connecticut. Included are the record of information on each structure and photographs for each structure.				
14. SUBJECT TERMS Westport Quadrangle; coastal regions; structures			15. NUMBER OF PAGES 28	
			16. PRICE CODE	
17. SECURITY CLASSIFICATION OF REPORT Unclassified	18. SECURITY CLASSIFICATION OF THIS PAGE Unclassified	19. SECURITY CLASSIFICATION OF ABSTRACT Unclassified	20. LIMITATION OF ABSTRACT	

GENERAL INSTRUCTIONS FOR COMPLETING SF 298

The Report Documentation Page (RDP) is used in announcing and cataloging reports. It is important that this information be consistent with the rest of the report, particularly the cover and title page. Instructions for filling in each block of the form follow. It is important to *stay within the lines* to meet optical scanning requirements.

Block 1. Agency Use Only (Leave blank).

Block 2. Report Date. Full publication date including day, month, and year, if available (e.g. 1 Jan 88). Must cite at least the year.

Block 3. Type of Report and Dates Covered. State whether report is interim, final, etc. If applicable, enter inclusive report dates (e.g. 10 Jun 87 - 30 Jun 88).

Block 4. Title and Subtitle. A title is taken from the part of the report that provides the most meaningful and complete information. When a report is prepared in more than one volume, repeat the primary title, add volume number, and include subtitle for the specific volume. On classified documents enter the title classification in parentheses.

Block 5. Funding Numbers. To include contract and grant numbers; may include program element number(s), project number(s), task number(s), and work unit number(s). Use the following labels:

C - Contract	PR - Project
G - Grant	TA - Task
PE - Program Element	WU - Work Unit Accession No.

Block 6. Author(s). Name(s) of person(s) responsible for writing the report, performing the research, or credited with the content of the report. If editor or compiler, this should follow the name(s).

Block 7. Performing Organization Name(s) and Address(es). Self-explanatory.

Block 8. Performing Organization Report Number. Enter the unique alphanumeric report number(s) assigned by the organization performing the report.

Block 9. Sponsoring/Monitoring Agency Name(s) and Address(es). Self-explanatory.

Block 10. Sponsoring/Monitoring Agency Report Number. (If known)

Block 11. Supplementary Notes. Enter information not included elsewhere such as: Prepared in cooperation with...; Trans. of...; To be published in.... When a report is revised, include a statement whether the new report supersedes or supplements the older report.

Block 12a. Distribution/Availability Statement. Denotes public availability or limitations. Cite any availability to the public. Enter additional limitations or special markings in all capitals (e.g. NOFORN, REL, ITAR).

DOD - See DoDD 5230.24, "Distribution Statements on Technical Documents."

DOE - See authorities.

NASA - See Handbook NHB 2200.2.

NTIS - Leave blank.

Block 12b. Distribution Code.

DOD - Leave blank.

DOE - Enter DOE distribution categories from the Standard Distribution for Unclassified Scientific and Technical Reports.

NASA - Leave blank.

NTIS - Leave blank.

Block 13. Abstract. Include a brief (Maximum 200 words) factual summary of the most significant information contained in the report.

Block 14. Subject Terms. Keywords or phrases identifying major subjects in the report.

Block 15. Number of Pages. Enter the total number of pages.

Block 16. Price Code. Enter appropriate price code (NTIS only).

Blocks 17. - 19. Security Classifications. Self-explanatory. Enter U.S. Security Classification in accordance with U.S. Security Regulations (i.e., UNCLASSIFIED). If form contains classified information, stamp classification on the top and bottom of the page.

Block 20. Limitation of Abstract. This block must be completed to assign a limitation to the abstract. Enter either UL (unlimited) or SAR (same as report). An entry in this block is necessary if the abstract is to be limited. If blank, the abstract is assumed to be unlimited.

SECTION 22
CONNECTICUT COASTAL STRUCTURES INVENTORY STUDY
PHASE III

APPENDIX O
WESTPORT QUADRANGLE

RECORDS OF STRUCTURES WITH PHOTOGRAPHS

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASSACHUSETTS

INVENTORY NUMBER: 1.00

QUAD : WESTPORT
ADDRESS: 1177 FAIRFIELD BCH RD
TOWN : FAIRFIELD STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : SEPARATES LAND AND WATER, PREVENTS EROSION AND FLO
MATERIAL : STELL ON WOOD

DESCRIPTION

L(FT)= 50
W(FT)= 0.5-1
H(FT ABOVE MHW)= 3

INSPECTION DATE : 06/21/89 INSPECTION TIME: 1510

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 103 NEG#8 LOOKING EAST
#2
#3
#4
#5

COMMENTS

INVENTORY NUMBER: 2.00

QUAD : WESTPORT
ADDRESS: 1187 FAIRFIELD BCH RD
TOWN : FAIRFIELD STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER, PREVENTS EROSION AND FLO
MATERIAL : CEMENT BLOCKS

DESCRIPTION

L(FT)= 60
W(FT)= 0.5
H(FT ABOVE MHW)= 5

INSPECTION DATE : 06/21/89 INSPECTION TIME: 1520

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 103 NEG#9 LOOKING WEST
#2
#3
#4
#5

COMMENTS

INVENTORY NUMBER: 3.00

QUAD : WESTPORT
ADDRESS: 1197 FAIRFIELD BCH RD
TOWN : FAIRFIELD STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER, PREVENTS EROSION AND FLO
MATERIAL : CONCRETE

DESCRIPTION

L(FT)= 50
W(FT)= 1.5
H(FT ABOVE MHW)= 3

INSPECTION DATE : 06/21/89 INSPECTION TIME: 1525

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 103 NEG#10 NORTH
#2
#3
#4
#5

COMMENTS

BURIED ALMOST COMPLETELY BY SAND

INVENTORY NUMBER: 4.00

QUAD : WESTPORT
ADDRESS: 1221-1291 FAIRFIELD BCH RD
TOWN : FAIRFIELD STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER, PREVENTS EROSION AND FLO
MATERIAL : CONC., CEM. BLOCK

DESCRIPTION

L(FT) = 390
W(FT) = 1.5
H(FT ABOVE MHW) = 5-6

INSPECTION DATE : 06/21/89 INSPECTION TIME: 1530

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 103 NEG#11 LOOKING WEST AT THE BEGINNING OF THE WALL
#2 ROLL 103 NEG#12 LOOKING EAST AT THE FAR END OF THE WALL
#3
#4
#5

COMMENTS

AT THE BEGINNING SAND ALMOST COVERS THE WALL, AT THE END THE
WALL IS ABOUT 5-6 FT ABOVE THE SAND.

INVENTORY NUMBER: 5.00

QUAD : WESTPORT
ADDRESS: 1255 FAIRFIELD BCH RD
TOWN : FAIRFIELD STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN CONDITION: GOOD
MAIN FUNCTION : TRAPS LITTORAL DRIFT, RETARDS SHORE EROSION
MATERIAL : STONE BLOCKS

DESCRIPTION

L(FT)= 300
W(FT)= 25
H(FT ABOVE MHW)= 0-5

INSPECTION DATE : 06/21/89 INSPECTION TIME: 1600

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PUBLIC
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 103 NEG#13 LOOKING EAST
#2
#3
#4
#5

COMMENTS

INVENTORY NUMBER: 6.00

QUAD : WESTPORT
ADDRESS: 1291 FAIRFIELD BCH RD
TOWN : FAIRFIELD STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN CONDITION: POOR
MAIN FUNCTION : TRAPS LITTORAL DRIFT, RETARDS SHORE EROSION
MATERIAL : TIMBER PILE

DESCRIPTION

L(FT)= 80
W(FT)= 0.3
H(FT ABOVE MHW)= 1

INSPECTION DATE : 06/21/89 INSPECTION TIME: 1605

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 103 NEG#14 LOOKING SOUTHEAST
#2
#3
#4
#5

COMMENTS

INVENTORY NUMBER: 7.00

QUAD : WESTPORT
ADDRESS: 1299 FAIRFIELD BCH RD
TOWN : FAIRFIELD STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER, PREVENTS EROSION AND FLO
MATERIAL : WOOD

DESCRIPTION

L(FT)= 55
W(FT)= NOT APPLICABLE
H(FT ABOVE MHW)= 7-8

INSPECTION DATE : 06/21/89 INSPECTION TIME: 1610

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 103 NEG#15 LOOKING NORTHWEST
#2
#3
#4
#5

COMMENTS

INVENTORY NUMBER: 8.00

QUAD : WESTPORT
ADDRESS: 1337 FAIRFIELD BCH RD
TOWN : FAIRFIELD STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER, PREVENTS EROSION AND FLO
MATERIAL : STONE IN CEMENT

DESCRIPTION

L(FT)= 55
W(FT)= 2 (WHERE APPLICABLE)
H(FT ABOVE MHW)= 7-8

INSPECTION DATE : 06/21/89 INSPECTION TIME: 1610

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 103 NEG#16 LOOKING NORTH
#2
#3
#4
#5

COMMENTS

INVENTORY NUMBER: 9.00

QUAD : WESTPORT
ADDRESS: 1347 FAIRFIELD BCH RD
TOWN : FAIRFIELD STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER, PREVENTS EROSION AND FLO
MATERIAL : CONCRETE

DESCRIPTION

L(FT)= 20
W(FT)= 0.5
H(FT ABOVE MHW)= 6

INSPECTION DATE : 06/21/89 INSPECTION TIME: 1615

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 103 NEG#17 LOOKING NORTH
#2
#3
#4
#5

COMMENTS

INVENTORY NUMBER: 10.00

QUAD : WESTPORT
ADDRESS: 1361-1381 FAIRFIELD BCH RD
TOWN : FAIRFIELD STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: FAIR
MAIN FUNCTION : SEPARATES LAND AND WATER, PREVENTS EROSION AND FLOODING
MATERIAL : CONCRETE

DESCRIPTION

L(FT) = 120
W(FT) = 1 (WHERE APPLICABLE)
H(FT ABOVE MHW) = 4-5

INSPECTION DATE : 06/21/89 INSPECTION TIME: 1620

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 103 NEG#18 LOOKING NORTHWEST
#2 ROLL 103 NEG#19 LOOKING NORTHEAST
#3
#4
#5

COMMENTS

INVENTORY NUMBER: 11.00

QUAD : WESTPORT
ADDRESS: SASCO HILL BEACH
TOWN : FAIRFIELD STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN CONDITION: FAIR
MAIN FUNCTION : TRAPS LITTORAL DRIFT, RETARDS SHORE EROSION
MATERIAL : STONE BLOCKS

DESCRIPTION

L(FT)= 400
W(FT)= 30
H(FT ABOVE MHW)= 0-7

INSPECTION DATE : 07/06/89 INSPECTION TIME: 845

- LAND CLASSIFICATION -

PERMIT NUMBER: 53131
OWNER'S NAME : PUBLIC
ACCESS : PUBLIC
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 106 NEG#10 LOOKING NORTHEAST
#2 ROLL 106 NEG#11 LOOKING SOUTHWEST
#3
#4
#5

COMMENTS

1953 PERMIT WAS FOR A LENGTH OF 300 FT
ORIGINAL GROIN WAS CONSTRUCTED OF RAILROAD TIES; L=200 FT,
PERMIT #52-54, DATED 4/1/52

INVENTORY NUMBER: 12.00

QUAD : WESTPORT
ADDRESS: FAIRFIELD COUNTRY CLUB
TOWN : FAIRFIELD STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: BREAKWATER CONDITION: GOOD
MAIN FUNCTION : PROTECTS HARBOR/ANCHORAGE BY INTERCEPTING WAVES
MATERIAL : STONE BLOCKS

DESCRIPTION

L(FT)= 1320
W(FT)= 20
H(FT ABOVE MHW)= 3

INSPECTION DATE : 07/06/89 INSPECTION TIME: 930

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PUBLIC
ACCESS : PRIVATE
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 106 NEG#12 LOOKING WEST
#2
#3
#4
#5

COMMENTS

INVENTORY NUMBER: 13.00

QUAD : WESTPORT
ADDRESS: 350 WILLOW ST
TOWN : FAIRFIELD STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER, PREVENTS EROSION AND FLO
MATERIAL : STONE IN CEMENT

DESCRIPTION

L(FT)= 1300
W(FT)= 1-3 (VARIES)
H(FT ABOVE MHW)= 5-3

INSPECTION DATE : 07/06/89 INSPECTION TIME: 1015

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 106 NEG#13 LOOKING NORTHWEST
#2 ROLL 106 NEG#14 LOOKING WEST
#3 ROLL 106 NEG#15 LOOKING NORTHWEST
#4 ROLL 106 NEG#16 LOOKING NORTHWEST
#5

COMMENTS

TOPPED BY A WALK. PARTS OF THE WALL ARE BLOCKED BY LARGE ROCK

INVENTORY NUMBER: 14.00

QUAD : WESTPORT
ADDRESS: 1201 PIQUOT AVE
TOWN : FAIRFIELD STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL/RIPRAP CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER, PREVENTS EROSION AND FLO
MATERIAL : CONCRETE

DESCRIPTION

L(FT)= 560
W(FT)= 6.5-11
H(FT ABOVE MHW)= 3-5

INSPECTION DATE : 07/06/89 INSPECTION TIME: 1030

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 106 NEG#17 LOOKING NORTH
#2
#3
#4
#5

COMMENTS

EXTRA 1.5 FOOT WIDTH AT THE BOTTOM. PROTECTIVE RIPRAP IN
FRONT OF IT, AND A STONE IN CEMENT WALL 2 FEET HIGH AND
1 FOOT WIDE ON TOP BORDERING LAWNS.

INVENTORY NUMBER: 15.00

QUAD : WESTPORT
ADDRESS: 1201 PIQUOT AVE
TOWN : FAIRFIELD STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN CONDITION: GOOD
MAIN FUNCTION : TRAPS LITTORAL DRIFT, RETARDS SHORE EROSION
MATERIAL : CONCRETE

DESCRIPTION

L(FT)= 85
W(FT)= 7
H(FT ABOVE MHW)= 0-4

INSPECTION DATE : 07/06/89 INSPECTION TIME: 1045

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 106 NEG#18 LOOKING WEST
#2
#3
#4
#5

COMMENTS

INVENTORY NUMBER: 16.00

QUAD : WESTPORT
ADDRESS: 1227 PIQUOT AVE
TOWN : FAIRFIELD STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: GROIN CONDITION: GOOD
MAIN FUNCTION : TRAPS LITTORAL DRIFT, RETARDS SHORE EROSION
MATERIAL : CONCRETE

DESCRIPTION

L(FT) = 75
W(FT) = 7
H(FT ABOVE MHW) = 0-4

INSPECTION DATE : 07/06/89 INSPECTION TIME: 1045

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 106 NEG#19 LOOKING SOUTHWEST
#2
#3
#4
#5

COMMENTS

INVENTORY NUMBER: 17.00

QUAD : WESTPORT
ADDRESS: 1259-1261 PIQUOT AVE
TOWN : FAIRFIELD STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER, PREVENTS EROSION AND FLO
MATERIAL : STONE IN CEMENT

DESCRIPTION

L(FT)= 310
W(FT)= 2
H(FT ABOVE MHW)= 10

INSPECTION DATE : 07/06/89 INSPECTION TIME: 1050

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RESIDENTIAL

- PHOTOS -

#1 ROLL 106 NEG#20 LOOKING WEST
#2
#3
#4
#5

COMMENTS

INVENTORY NUMBER: 18.00

QUAD : WESTPORT
ADDRESS: SOUTHPORT BEACH/SEA LODGE
TOWN : FAIRFIELD STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: SEAWALL CONDITION: GOOD
MAIN FUNCTION : SEPARATES LAND AND WATER, PREVENTS EROSION AND FLO
MATERIAL : STONE IN CEMENT

DESCRIPTION

L(FT)= 55
W(FT)= NOT APPLICABLE
H(FT ABOVE MHW)= 6

INSPECTION DATE : 07/06/89 INSPECTION TIME: 1100

- LAND CLASSIFICATION -

PERMIT NUMBER: 0
OWNER'S NAME : PRIVATE
ACCESS : PRIVATE
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 106 NEG#21 LOOKING NORTH
#2
#3
#4
#5

COMMENTS

INVENTORY NUMBER: 19.00

QUAD : WESTPORT
ADDRESS: SOUTHPORT BEACH
TOWN : FAIRFIELD STATE : CT
COUNTY : FAIRFIELD

- STRUCTURAL INVESTIGATIONS -

TYPE OF STRUCTURE: REVETMENT CONDITION: GOOD
MAIN FUNCTION : FACING ON SLOPE WHICH PREVENTS EROSION
MATERIAL : STONE IN CEMENT

DESCRIPTION

L(FT)= 450
W(FT)= NOT APPLICABLE
H(FT ABOVE MHW)= 6

INSPECTION DATE : 07/06/89 INSPECTION TIME: 1105

- LAND CLASSIFICATION -


PERMIT NUMBER: 0
OWNER'S NAME : PUBLIC
ACCESS : PUBLIC
LAND USE : RECREATIONAL

- PHOTOS -

#1 ROLL 106 NEG#22 LOOKING WEST
#2
#3
#4
#5

COMMENTS


WE 1 #1



WE 2 #1




WE 3 #1



WE 4 #1



WE 4 #2




WE 5 #1



WE 6 #1



WE 7 #1




WE 8 #1



WE 9 #1




WE 10 # 1



WE 10 #2




WE 11 #1



WE 11 #2




WE 12 #1



WE 13 #1



WE 13 #2



WE 13 #3



WE 13 #4



WE 14 #1




WE 15 #1




WE 16 #1



WE 17 #1



WE 18 #1



WE 19 #1

